Approved For Release 2002 0 1 : CIA-RDP61-00763A000100050081-0

DPD 1385-59 Cy 4 of 5

25X1A Elint Equipment Malfunction Report for February 1959 Detaciment C - Some interference was encountered between 25X1A equipments in airereft 370. Corrective action is being taken but has not been completed as of this isto. Betachment B - A resulated 150 wolt supply failed in 25X1A equipment while on test flight. The supply was repaired and is now functioning properly. 25X1A Matribution: Orig & 1 - Addressee 3 - 0-15 4 - M

5 - Chrona

A.W.R./be